



Accessories

Accesorios

Accessoires

Acessórios

ZDM

ZDM 6

ZDM 8






ZDM 12

ZDM 13

ZDM 20

ZDM 25

ZDM 32



ZDM	Pressure gauge	Manómetro	Manomètre	Manômetro
(03)	Configured with green/red scale	Configurado con escala verde/roja	Exécution avec plage verte/rouge	Configurado segundo escala verde/vermelha
(22)	Fluid damped	Vaciado por fluido	Exécution avec glycé rine	Fluido espirado
(51)	Configuration with accessories	Configuración con accesorios	Exécution avec accessoires	Configuração com acessórios
SW	Wrench size	Tamaño llave	Côte six pans	Tamanho da ligação

ZDM		S	[inches]						ZDM (51)	T
			a	b	c	Ø d	e	SW		
8 (01)	730982	R 1/4	1.97	1.18	-	2.17	-	0.55	6	208352 R 1/8
8 (03)	730673	R 1/4	1.97	1.18	-	2.17	-	0.55	8	208353 R 1/4
8 (22)	730620	R 1/4	-	1.30	3.44	2.48	0.91	0.67	12	208354 R 3/8
13 (22)	730624	R 1/2	-	2.32	5.59	3.94	0.98	1.06	13	208355 R 1/2
									20	208356 R 3/4
									25	208357 R 1
									32	208358 R 1 1/4

G = straight thread, non-sealing

R = NPT self sealing

ZA 918

1.1.97

Rietschle Inc.

7222 Parkway Drive
Hanover, MD 21076 USA

☎ 410-712-4100

Fax 410-712-4148

E-Mail:

info@rietschlepumps.com

http://

www.rietschlepumps.com